

Economy Services, Inc.



17 April, 2007

Radon

Bob Thompson
Mountain Home Properties
61 Riverside Villa Drive
Maggie Valley, NC 28751

RE: Inspection #14274
24 White Willow Ridge
Black Mountain, NC
Radon Kit: #4116547 & #4116548
Result: 1.0 pCi/L & 0.9 pCi/L

Dear Mr. Thompson:

Enclosed is the original report from the radon lab for the above referenced property.

EPA recommends that **4.0 pCi/L** be used as a target for corrective action. This means that you should try to permanently reduce your levels to about 4 pCi/L or below in the lived-in areas of the above referenced property if your results exceed this level.

If you have any questions, please call.

Constructively,

W. Douglas Jones
W. Douglas Jones

Enclosure

April 17, 2007

**** LABORATORY ANALYSIS REPORT ****

Pg 1 of 1

P835 / DEBBIE JONES / ECONOMY SERVICES, INC

Kit #	pCi/L	Hours	Started	Ended	Analyzed	NOTES	MST%	°F
4116547	1.0 ± 0.1	50	2007-04-12 @ 1:00 pm	2007-04-14 @ 3:00 pm	2007-04-17		6.0%	50
4116548	0.9 ± 0.1	50	2007-04-12 @ 1:00 pm	2007-04-14 @ 3:00 pm	2007-04-17		5.5%	50

Air Chek, Inc. 1936 Butler Bridge Rd, Fletcher, NC 28732-8792 Phone: (828) 684-0893 Fax: (828) 684-8498